

Microwave & Electronic Light Control Fix

The kit includes a clamp and a piece of wire. The clamp fastens the wire to the base of the second temp sensor (Th-2). The other end of the wire is connected to the ground lug located in the bottom of the unit. No wires are removed to install this kit.

The problem occurs when a microwave or electronic light control create a signal on the same frequency the Seisco uses to monitor its sensors. The Seisco boiler just doesn't know which signal to listen to. The kit when applied enables the Seisco to listen to its own sensors.

